2

SEM® 2K LOWER PANEL PROTECTION STANDARD OPERATING PROCEDURE



Clean with **Scuff & Clean** and gray scuff pad. Rinse with water and dry. Clean with **SEM Solve** or **XXX** Universal Surface Cleaner. Wipe clean in one direction with clean. lint-free cloth.

Sand with P180 - P220 grit. Re-clean with SEM

Solve or XXX Universal Surface Cleaner. Wipe clean in one direction with clean, lint-free cloth. (i) "Back-taping" helps eliminate any heavy edges and provides smooth transition to other surfaces. Prime bare metal with a direct-to-metal epoxy or 2K urethane primer. Allow primer to fully cure.


PRODUCT LIST



PREP

Part	Product	Size
38391	Scuff & Clean	Gallon Pump
38398	Scuff & Clean	16 oz. Tube
38371	SEM Solve	Gallon
38373	SEM Solve	20 oz. Aerosol
38374	SEM Solve	Square Quart
77771	XXX Universal Surface Cleaner	Gallon
77774	XXX Universal Surface Cleaner	Quart







PRIME

Product	Size
Netalock™ DTM High Build Primer Kit	1.25 Gallon
Metalock DTM High Build Primer	Quart
Netalock DTM Hardener	Half Pint
Vorld Class™ DTM Primer	Gallon
Vorld Class DTM Primer	Quart
Vorld Class DTM Primer Activator	Cone Quart
Vorld Class DTM Primer Activator	Half Pint
1	letalock™ DTM High Build Primer Kit Netalock DTM High Build Primer Netalock DTM Hardener Vorld Class™ DTM Primer Vorld Class DTM Primer Vorld Class DTM Primer Activator



APPLY

Part	Product	Size
40820	Pro-Tex™ 2K Chip Guard	3 Pint Kit

EQUIPMENT

Part	Product	Size
71109	Premium Undercoat Gun	1 Applicator
71004	Plastic Schutz Bottle	1 Bottle
77743	XXX Gun Cleaner	20 oz. Aerosol
77763	XXX Universal Gun Cleaner	20 oz. Aerosol

SEM Products, Inc.

Rock Hill, SC 29730 Tech Support: 1-800-831-1122 Customer Care: 1-866-327-7829 semproducts.com



MIX

APPLY HEAVY TEXTURE

Using a Premium Undercoat Gun & Plastic

Air Pressure: 45 - 90 psiDistance: 18" - 24"Coats:

Flash time: $10 - 20 \, \text{min}$ Topcoat: 30 min

Dust free: $60 - 90 \, \text{min}$



Using a Spray Gun

Schutz Bottle

Fluid Tip: 1.8 - 2.5**Air Pressure:** 45 - 90 psiDistance: 8'' - 10''Coats: 2

Flash time: 10 - 20 minTopcoat: 30 min **Dust Free:** $60 - 90 \, \text{min}$



Remove masking tape while final coat is still wet. Clean gun with XXX Gun Cleaner or XXX Universal Gun Cleaner.

WATCH THE VIDEO AT:

semproducts.com/sop-2k-lowerpanel-protection